



SDMS DocID

2205022

MC0983

- Task 1 & 2

MC0983

- Task 1 & 2

MC0983

- Task 3

MC0983

- Task 3

MC0983

- Task 3

MC0983

- Task 3

MC0983

- Task 3

FEDERAL EXPRESS

PLEASE COMPLETE ALL INFORMATION IN THE 5 BLOCKS OUTLINED IN ORANGE
SEE BACK OF FORM SET FOR COMPLETE PREPARATION INSTRUCTIONS.

AIRBILL NUMBER

226215754



00630

YOUR FEDERAL EXPRESS ACCOUNT NUMBER

00630-003229

DATE

10-7-83

FROM (Your Name)

COMPANY

ENVIRODYNE ENGINEERS

DEPARTMENT/FLOOR NO.

STREET ADDRESS

12161 LACKLAND

CITY

ST. LOUIS

STATE

MO

TO (Recipient's Name)

Russ Sloboda

COMPANY

NUS Corporation

NUS CORPORATION

STREET ADDRESS (P.O. BOX NUMBERS ARE NOT DELETABLE)

992 Old Eagle School Rd

CITY

Wayne

STATE

PA

AIRBILL NO.

226215754

ZIP ACCURATE ZIP CODE REQUIRED FOR CORRECT INVOICING

63101

IN TENDERING THIS SHIPMENT, SHIPPER AGREES THAT F.E.C. SHALL NOT BE LIABLE FOR SPECIAL, INCIDENTAL, OR CONSEQUENTIAL DAMAGES ARISING FROM

ZIP ACCURATE ZIP CODE REQUIRED FOR OVERNIGHT DELIVERY

19087

YOUR NOTES/REFERENCE NUMBERS (FIRST 12 CHARACTERS WILL ALSO APPEAR ON INVOICE)

619C

PAYMENT ☒ Bill Shipper

☐ Bill Recipient's F.E.C. Acct.

☐ Bill 3rd Party F.E.C. Acct.

☐ Bill Credit Card

☐ Cash In Advance

Account Number/Credit Card Number

CARRIAGE HEREOF, F.E.C. DIS- CLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, WITH RESPECT TO THIS SHIPMENT. THIS IS A NON-NEGOTIABLE AIRBILL SUBJECT TO CONDITIONS OF CONTRACT SET FORTH ON REVERSE OF SHIPPER'S COPY. UNLESS YOU DECLARE A HIGHER VALUE, THE LIABILITY OF FEDERAL EXPRESS CORPORATION IS LIMITED TO \$100.00.

FEDERAL EXPRESS USE

FREIGHT CHARGES

DECLARED VALUE CHARGE

SERVICES CHECK ONLY ONE BOX

PRIORITY ONE (P-1)

☒ (OVERNIGHT PACKAGES) 6 ☐

COURIER PAK 7 ☐

2 ☐ OVERNIGHT ENVELOPE (up to 1 LB.) 8 ☐

3 ☐ OVERNIGHT BOX (up to 5 LBS.) 9 ☐

4 ☐ OVERNIGHT TUBE (up to 5 LBS.)

STANDARD AIR

5 ☐ DELIVERY 2ND BUSINESS DAY FOLLOWING PICK UP

DELIVERY AND SPECIAL HANDLING CHECK SERVICES REQUIRED

1 ☐ HOLD FOR PICK-UP AT FOLLOWING FEDERAL EXPRESS LOCATION SHOWN IN SERVICE GUIDE

2 ☒ DELIVER

3 ☐ SATURDAY SERVICE REQUIRED See Reverse (Extra charge applies for delivery)

4 ☒ RESTRICTED ARTICLES SERVICE (P-1 and Standard Air Packages only, extra charge)

5 ☐ SSS (Signature Security Service required, extra charge applies)

6 ☐ DRY ICE LBS

7 ☐ OTHER SPECIAL SERVICE

8 ☐

9 ☐

PIECES

WEIGHT

DECLARED VALUE

O/S

EMP. NO.

DATE

☐ CASH RECEIVED

☐ RETURN TO SHIPPER

☐ THIRD PARTY

☐ CHG. TO DEL. ☐ CHG. TO HOLD

STREET ADDRESS

CITY

STATE

ZIP

RECEIVED BY: (Signature)

X

DATE/TIME Federal Express Use

DATE/TIME RECEIVED

F.E.C. EMPLOYEE NUMBER

"OVERNIGHT" IS DEFINED AS NEXT BUSINESS DAY (MONDAY THROUGH FRIDAY). SEE SPECIAL HANDLING FOR SATURDAY DELIVERY.

PART # 2041734049
REVISION DATE 5-15-80
PRINTED USA

RECIPIENT COPY (AFFIXED TO PACKAGE, GIVEN TO RECIPIENT AT DELIVERY)

1. In tendering the shipment for carriage the shipper agrees to these TERMS AND CONDITIONS OF CONTRACT which no agent or employee of the parties may alter and that this Federal Express Airbill is NON-NEGOTIABLE and has been prepared by him or on his behalf by Federal Express.

2. The Shipper agrees that carriage is subject to terms and conditions of contract stated herein and those terms and conditions which are also stated in the most recent Federal Express Service Guide, which is available for inspection and incorporated into this contract by reference.

3. In tendering the shipment for carriage, **THE SHIPPER WARRANTS** that the shipment is packaged adequately to protect the enclosed goods and to insure safe transportation with ordinary care and handling, and that each package is appropriately labeled and is in good order (except as noted) for carriage as specified.

4. When the destination of the shipment is not within the Federal Express air terminal zone as listed in the most recent Federal Express Service Guide, Federal Express makes no commitment with respect to time of delivery of the shipment.

5. In the event of international carriage of any shipment hereunder, the rules relating to liability established by the Convention for the Unification of Certain Rules Relating to International Carriage by Air signed at Warsaw, Poland on October 12, 1929 shall apply to the carriage insofar as the same is governed thereby.

6. Federal Transportation Excise Tax: Pursuant to Section 4271 of the Internal Revenue Code, a 5% tax on air transportation portion of the service and the accessory services related thereto is included within the basic rate.

7. **DECLARED VALUE AND LIMITATION OF LIABILITY: THE LIABILITY OF FEDERAL EXPRESS IS LIMITED TO THE SUM OF \$100.00** unless a higher value is declared for carriage herein and a greater charge paid at the rate of 30¢ per \$100.00 value. In the case of P-1 service the maximum higher declared value is \$5000.00. In the case of Courier-Pak or Standard Air Service, the maximum higher declared value is \$2,000.00. Shipments containing items of extraordinary value, including, but not limited to, drawings, paintings, sculptures, porcelain, ceramics, furs, jewelry, fur trimmed clothing, watches, gems, stones, money, bullion, currency, coins, trading stamps, or other extraordinary valuable items, are limited to a maximum declared value of \$500.00. In the case of P-1 service when multiple shipments are placed on a single airbill but the shipper has not specified the declared value of each individual shipment, the declared value for each individual shipment will be determined by dividing the total declared value on the airbill by the number of shipments indicated on the airbill, subject to a \$100.00 minimum declared value per individual shipment. In the case of Standard Air Service, when the shipment consists of two or more pieces, the declared value for each piece will be determined by dividing the declared value on the airbill by the number of pieces in the shipment. The liability of Federal Express is limited to the declared value of the shipment or the amount of loss or damage actually sustained, whichever is lower.

Federal Express is not liable for loss, damage, delay, mis-delivery or non-delivery not caused by its own negligence or any loss, damage, delay, mis-delivery or non-delivery caused by the act, default or omission of the shipper, consignee, or any other party who claims interest in the shipment, the nature of the shipment or any defect, characteristic of inherent vice thereof, violation by the shipper or consignee of any of the conditions of contract contained in this airbill or in the Federal Express

Service Guide; including, but not limited to, improper or insufficient packing, securing, marking or addressing, or failure to observe any of the rules relating to shipments not acceptable for transportation or shipments acceptable only under certain conditions; acts of God, perils of the air, public enemies, public authorities acting with actual or apparent authority, authority of law, acts or omissions of customs or quarantine officials, riots, strikes or other local disputes, civil commotions, hazards incident to a state of war, weather conditions or mechanical delay of the aircraft or acts or omissions of any person other than FEC, including compliance with delivery instructions from the shipper or consignee. FEC shall not be liable for the loss of articles loaded and sealed in packages by the shipper provided the seal is unbroken at the time of delivery and the package retains its basic integrity. **FEDERAL EXPRESS SHALL NOT BE LIABLE IN ANY EVENT FOR ANY SPECIAL, INCIDENTAL OR CONSEQUENTIAL DAMAGES, INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS OR INCOME WHETHER OR NOT FEDERAL EXPRESS HAD KNOWLEDGE THAT SUCH DAMAGES MIGHT BE INCURRED.**

8. **CLAIMS: WRITTEN NOTICE OF LOSS DUE TO DAMAGE, SHORTAGE OR DELAY MUST BE REPORTED BY THE SHIPPER WITHIN 15 DAYS AFTER THE DELIVERY OF THE SHIPMENT. WRITTEN NOTICE OF LOSS DUE TO NON-DELIVERY MUST BE REPORTED BY THE SHIPPER WITHIN 90 DAYS AFTER ACCEPTANCE OF THE SHIPMENT OR CARRIAGE.** Written notification will be considered to have been made if the shipper calls and notifies the Customer Services Department at 800/238-5355 (in Tennessee 800/542-5171) and as soon as practicable thereafter files a written notification. Documentation of all claims other than overcharge claims must be submitted in writing to FEC within ninety (90) days after receipt of written notification. No claim for damage will be entertained until all transportation charges have been paid. The amount of a claim may not be deducted from the transportation charges. Receipt of the shipment by the consignee without written notification of damage on the delivery receipt shall be prima facie evidence that the shipment was delivered in good condition, except that in the case of claims for concealed damage which is not discovered at the time of delivery, the shipper shall notify FEC in writing as promptly as possible after the discovery thereof and in any event not later than 15 days from the date of delivery. The shipper must make the original shipping cartons and packing available for inspection by FEC. Claims for overcharges and refunds must be made in writing to FEC within twelve (12) months of the billing date. All claims must be filed by the shipper.

9. All shipments are subject to inspection by FEC, including but not limited to opening the shipment. However, FEC is not obligated to perform such inspection.

10. C.O.D. services are not available, and a C.O.D. shipment sent in error will be delivered as a normal pre-paid or collect shipment.

11. Federal Express carries no cargo liability insurance but maintains a separate fund for the satisfaction of cargo claims which may arise out of the carriage of cargo pursuant to the conditions of contract contained herein and in the most recent Federal Express Service Guide.

12. Notwithstanding the shipper's instructions to the contrary, the shipper shall be primarily liable for all costs and expenses related to the shipment of the package, and for costs incurred in either returning the shipment to the shipper or warehousing the shipment pending disposition.

FEDERAL EXPRESS

PLEASE COMPLETE ALL INFORMATION IN THE 5 BLOCKS OUTLINED IN ORANGE.
SEE BACK OF FORM SET FOR COMPLETE PREPARATION INSTRUCTIONS.

147201143



YOUR FEDERAL EXPRESS ACCOUNT NUMBER
1059-6318-6

DATE
6-2-85

FROM (Your Name)
Eugene Dennis

TO (Recipient's Name)
Robert Beckman

If Hold For Recipient, Saturday Delivery, Recipient's Phone Number

COMPANY
NHS CORPORATION

COMPANY
V...

DEPARTMENT/FLOOR NO.

STREET ADDRESS
992 OLD EAGLE SCHOOL RD #916

STREET ADDRESS (P.O. BOX NUMBERS ARE NOT DELIVERABLE)
6000 1st Ave NE

CITY
WAYNE

CITY
SPRINGFIELD

STATE

AIRBILL NO. **147201143**

ZIP, ACCURATE ZIP CODE REQUIRED FOR CORRECT DELIVERY
190057

IN TENDERING THIS SHIPMENT, SHIPPER AGREES THAT F.E.C. SHALL NOT BE LIABLE FOR SPECIAL, INCIDENTAL OR CONSEQUENTIAL DAMAGES ARISING FROM CARRIAGE HEREOF, F.E.C. DIS-

CLAIMS, ALL WARRANTIES, EXPRESS OR IMPLIED, WITH RESPECT TO THIS SHIPMENT. THIS IS A NON-NEGOTIABLE AIRBILL SUBJECT TO CONDITIONS OF CONTRACT SET FORTH ON REVERSE OF SHIPPER'S COPY. UNLESS YOU DECLARE A HIGHER VALUE, THE LIABILITY OF FEDERAL EXPRESS CORPORATION IS LIMITED TO \$100.00. FEDERAL EXPRESS DOES NOT CARRY CARGO LIABILITY INSURANCE.


YOUR NOTES/REFERENCE NUMBERS (FIRST 12 CHARACTERS WILL ALSO APPEAR ON INVOICE)
8306-20

PAYMENT ☒ Bill Shipper ☐ Bill Recipient's F.E.C. Acct. ☐ Bill 3rd Party F.E.C. Acct. ☐ Bill Credit Card
☐ Cash In Advance Account Number/Credit Card Number

SERVICES CHECK ONLY ONE BOX		DELIVERY AND SPECIAL HANDLING CHECK SERVICES REQUIRED	
PRIORITY 1 <input checked="" type="checkbox"/> OVERNIGHT PACKAGES (Up to 70 LBS.) <input type="checkbox"/> COURIER PAK 7 <input type="checkbox"/> OVERNIGHT ENVELOPE (Up to 2 LBS.) <input type="checkbox"/> OVERNIGHT BOX (Up to 5 LBS.) <input type="checkbox"/> OVERNIGHT TUBE (Up to 5 LBS.) STANDARD AIR <input type="checkbox"/> DELIVERY 2ND BUSINESS DAY FOLLOWING PICK-UP (Up to 70 LBS.) OVERNIGHT™ IS NEXT BUSINESS DAY (MONDAY THROUGH FRIDAY). TWO DAYS FROM ALASKA/HAWAII. SATURDAY DELIVERY AVAILABLE IN CONTINENTAL U.S. SEE "SPECIAL HANDLING."		<input type="checkbox"/> HOLD FOR PICK-UP AT FOLLOWING FEDERAL EXPRESS LOCATION SHOWN IN SERVICE GUIDE. RECIPIENT'S PHONE NUMBER IS REQUIRED. <input checked="" type="checkbox"/> DELIVER <input type="checkbox"/> SATURDAY SERVICE REQUIRED (See Reverse (Extra charge applies for delivery). <input type="checkbox"/> RESTRICTED ARTICLES SERVICE (P-1 and Standard Air Packages only, extra charge) <input type="checkbox"/> SSS (Signature Security Service required, extra charge applies) <input type="checkbox"/> DRY ICE _____ LBS. <input type="checkbox"/> OTHER SPECIAL SERVICE _____ <input type="checkbox"/> _____ <input type="checkbox"/> _____	

PACKAGES	WEIGHT	DECLARED VALUE	O/S
1			
2			
3			
4			
TOTAL	TOTAL	TOTAL	
RECEIVED AT SHIPPER'S DOOR <input type="checkbox"/> REGULAR STOP <input type="checkbox"/> NON-CALL STOP <input type="checkbox"/> F.E.C. LOC. Federal Express Corporation Employee No. 2255 DATE/TIME For Federal Express Use 6:24			

FEDERAL EXPRESS USE	
FREIGHT CHARGES	
DECLARED VALUE CHARGE	
AGT/PRO	ADVANCE ORIGIN
AGT/PRO	ADVANCE DESTINATION
OTHER	
TOTAL CHARGES	



PART #2041730751
FEC-S-0751 D/O/B
REVISION DATE
7-82 \$
PRINTED U.S.A.

SHIPPER'S COPY

FEDERAL EXPRESS

1. In tendering the shipment for carriage the shipper agrees to these TERMS AND CONDITIONS OF CONTRACT which no agent or employee of the parties may alter and that this Federal Express Airbill is NON-NEGOTIABLE and has been prepared by him or on his behalf by Federal Express.

2. The shipper agrees that carriage is subject to terms and conditions of contract stated herein and those terms and conditions which are also stated in the most recent Federal Express Service Guide, which is available for inspection and incorporated into this contract by reference.

3. In tendering the shipment for carriage, **THE SHIPPER WARRANTS** that the shipment is packaged adequately to protect the enclosed goods and to insure safe transportation with ordinary care and handling and that each package is appropriately labeled and is in good order (except as noted) for carriage as specified.

4. When the destination of the shipment is not within the Federal Express air terminal zone as listed in the most recent Federal Express Service Guide, Federal Express makes no commitment with respect to time of delivery of the shipment.

5. In the event of international carriage of any shipment hereunder, the rules relating to liability established by the Convention for the Unification of Certain Rules Relating to International Carriage by Air signed at Warsaw, Poland on October 12, 1929 shall apply to the carriage insofar as the same is governed thereby.

6. Federal Transportation Excise Tax. Pursuant to Section 4271 of the Internal Revenue Code, a 5% tax on air transportation portion of the service and the accessory services related thereto is included within the basic rate.

7. **DECLARED VALUE AND LIMITATION OF LIABILITY. THE LIABILITY OF FEDERAL EXPRESS IS LIMITED TO THE SUM OF \$100.00** unless a higher value is declared for carriage herein and a greater charge paid at the rate of 30¢ per \$100.00 value. The maximum higher declared value is \$5000.00. Shipments containing items of extraordinary value, including but not limited to; drawings, paintings, sculptures, porcelain, ceramics, furs, fur clothing, fur trimmed clothing, jewelry, watches, gems, stones (precious or semi-precious cut or uncut), industrial diamonds, costume jewelry, precious metals, gold, silver, (bullion, dust or precipitates), platinum (except as an integral part of electronic machinery), money, currency, coins, trading stamps, stocks, bonds, cash letters (or their equivalent) or other extraordinary valuable items, are limited to a maximum declared value of \$500.00. When multiple packages are placed on a single airbill but the shipper has not specified the declared value of each individual package, the declared value for each individual package will be determined by dividing the total declared value on the airbill by the number of packages indicated on the airbill, subject to a \$100.00 minimum declared value per individual package. The liability of Federal Express is limited to the declared value of the shipment or the amount of loss or damage actually sustained, whichever is lower.

Federal Express is not liable for loss, damage, delay, mis-delivery or non-delivery not caused by its own negligence or any loss, damage, delay, mis-delivery or non-delivery caused by the act, default or omission of the shipper, consignee, or any other party who claims interest in the shipment, the nature of the shipment or any defect, characteristic or inherent vice thereof; violation by the shipper or consignee of any of the conditions of contract contained in this airbill or in the Federal Express Service Guide, including, but not limited to, improper or insufficient packing, secur-

ing, marking or addressing, or failure to observe any of the rules relating to shipments not acceptable for transportation or shipments acceptable only under certain conditions, acts of God, perils of the air, public enemies, public authorities acting with actual or apparent authority, authority of law, acts or omissions of customs or quarantine officials, riots, strikes or other local disputes, civil commotions, hazards incident to a state of war, weather conditions or mechanical delay of the aircraft; or acts or omissions of any person other than FEC, including compliance with delivery instructions from the shipper or consignee. FEC shall not be liable for the loss of articles loaded and sealed in packages by the shipper provided the seal is unbroken at the time of delivery and the package retains its basic integrity. **FEDERAL EXPRESS SHALL NOT BE LIABLE IN ANY EVENT FOR ANY SPECIAL, INCIDENTAL OR CONSEQUENTIAL DAMAGES, INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS OR INCOME WHETHER OR NOT FEDERAL EXPRESS HAD KNOWLEDGE THAT SUCH DAMAGES MIGHT BE INCURRED.**


8. **CLAIMS. WRITTEN NOTICE OF LOSS DUE TO DAMAGE, SHORTAGE OR DELAY MUST BE REPORTED BY THE SHIPPER WITHIN 15 DAYS AFTER THE DELIVERY OF THE SHIPMENT. WRITTEN NOTICE OF LOSS DUE TO NON-DELIVERY MUST BE REPORTED BY THE SHIPPER WITHIN 180 DAYS AFTER ACCEPTANCE OF THE SHIPMENT OR CARRIAGE.** Written notification will be considered to have been made if the shipper calls and notifies the Customer Services Department at 800/238-5355 (in Tennessee 800/542-5171) and as soon as practicable thereafter files a written notification. Documentation of all claims other than overcharge claims must be submitted in writing to FEC within ninety (90) days after receipt of written notification. No claim for damage will be entertained until all transportation charges have been paid. The amount of a claim may not be deducted from the transportation charges. Receipt of the shipment by the consignee without written notification of damage on the delivery receipt shall be prima facie evidence that the shipment was delivered in good condition, except that in the case of claims for concealed damage which is not discovered at the time of delivery, the shipper shall notify FEC in writing as promptly as possible after the discovery thereof and in any event not later than 15 days from the date of delivery. The shipper must make the original shipping cartons and packing available for inspection by FEC. Claims for overcharges and refunds must be made in writing to FEC within twelve (12) months of the billing date. All claims must be filed by the shipper.

9. All shipments are subject to inspection by FEC, including but not limited to opening the shipment. However, FEC is not obligated to perform such inspection. 10. C.O.D. services are not available and a C.O.D. shipment sent in error will be delivered as a normal pre-paid or collect shipment.

11. Federal Express carries no cargo liability insurance but maintains a separate fund for the satisfaction of cargo claims which may arise out of the carriage of cargo pursuant to the conditions of contract contained herein and in the most recent Federal Express Service Guide.

12. Notwithstanding the shipper's instructions to the contrary, the shipper shall be primarily liable for all costs and expenses related to the shipment of the package, and for costs incurred in either returning the shipment to the shipper or warehouse, including the shipment pending disposition.

13. Saturday Delivery: Recipient's phone number is required.



PLEASE COMPLETE ALL INFORMATION IN THE 5 BLOCKS OUTLINED IN ORANGE
SEE BACK OF FORM SET FOR COMPLETE PREPARATION INSTRUCTIONS.

AIRBILL NUMBER

047201132

00190

YOUR FEDERAL EXPRESS ACCOUNT NUMBER

1050-0318-4

DATE

TO (Recipient's Name)

If Hold For Pick-Up on Saturday Delivery,
Recipient's Phone Number

COMPANY

DEPARTMENT/FLOOR NO.

STREET ADDRESS (P.O. BOX NUMBERS ARE NOT DELIVERABLE)

CITY

STATE

FROM (Your Name)

Eugene Dennis

COMPANY

DEPARTMENT/FLOOR NO.

WIS CORPORATION

STREET ADDRESS

992 OLD EAGLE SCHOOL RD 2916

CITY

STATE

WAYNE

PA

AIRBILL NO.

147201132

ZIP ACCURATE ZIP CODE REQUIRED
FOR CARRIER INVOICING
170087

IN TENDERING THIS SHIPMENT, SHIPPER AGREES THAT
F.E.C. SHALL NOT BE LIABLE FOR SPECIAL, INCIDENTAL OR CONSEQUENTIAL DAMAGES ARISING FROM
CARRIAGE HEREOF. F.E.C. DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, WITH
RESPECT TO THIS SHIPMENT. THIS IS A NON-NEGOTIABLE
AIRBILL SUBJECT TO CONDITIONS OF CONTRACT SET FORTH
ON REVERSE OF SHIPPER'S COPY. UNLESS YOU DECLARE A
HIGHER VALUE, THE LIABILITY OF FEDERAL EXPRESS CORPORATION IS LIMITED TO \$100.00. FEDERAL EXPRESS DOES
NOT CARRY CARGO LIABILITY INSURANCE.

ZIP ACCURATE ZIP CODE REQUIRED
FOR OVERNIGHT DELIVERY
170087

YOUR NOTES/REFERENCE NUMBERS (FIRST 12 CHARACTERS WILL ALSO APPEAR ON INVOICE)

8306-20 0500-01

PAYMENT ☒ Bill Shipper ☐ Bill Recipient's F.E.C. Acct. ☐ Bill 3rd Party F.E.C. Acct. ☐ Bill Credit Card

☐ Cash In Advance Account Number/Credit Card Number

FEDERAL EXPRESS USE

FREIGHT CHARGES

DECLARED VALUE CHARGE

SERVICES CHECK ONLY ONE BOX		DELIVERY AND SPECIAL HANDLING CHECK SERVICES REQUIRED	PACKAGES	WEIGHT	DECLARED VALUE	O/S
PRIORITY 1		HOLD FOR PICK-UP AT FOLLOWING: <input type="checkbox"/> FEDERAL EXPRESS LOCATION SHOWN IN SERVICE GUIDE. RECIPIENT'S PHONE NUMBER IS REQUIRED.	1	4.5		
1 <input checked="" type="checkbox"/> OVERNIGHT LETTER (Up to 70 LBS.)			TOTAL	TOTAL	TOTAL	
2 <input type="checkbox"/> OVERNIGHT ENVELOPE (Up to 2 LBS.)		2 <input checked="" type="checkbox"/> DELIVER				
3 <input type="checkbox"/> OVERNIGHT BOX (Up to 5 LBS.)		3 <input type="checkbox"/> SATURDAY SERVICE REQUIRED (See Reverse (Extra charge applies for delivery.))				
4 <input type="checkbox"/> OVERNIGHT TUBE (Up to 5 LBS.)		4 <input type="checkbox"/> RESTRICTED ARTICLES SERVICE (P-1 and Standard Air Packages only, extra charge)				
STANDARD AIR		5 <input type="checkbox"/> SSS (Signature Security Service required, extra charge applies)				
5 <input type="checkbox"/> DELIVERY 2ND BUSINESS DAY FOLLOWING PICK-UP (Up to 70 LBS.)		6 <input type="checkbox"/> DRY ICE _____ LBS.				
		7 <input type="checkbox"/> OTHER SPECIAL SERVICE				
		8 <input type="checkbox"/>				
		9 <input type="checkbox"/>				

RECEIVED AT
SHIPPER'S DOOR
☐ REGULAR STOP
☒ ON-CALL STOP
☐ F.E.C. LOC.

Federal Express Corporation Employee No.
22356

DATE/TIME For Federal Express Use
6-24



AGT/PRO	ADVANCE ORIGIN
AGT/PRO	ADVANCE DESTINATION
	OTHER
TOTAL CHARGES	
PART #2041730751 FEC-S-0751 D/OB REVISION DATE 7-82 \$ PRINTED U.S.A.	

SHIPPER'S COPY

1. In tendering the shipment for carriage, the shipper agrees to these TERMS AND CONDITIONS OF CONTRACT, which no agent or employee of the parties may alter and that this Federal Express Airbill is NON-NEGOTIABLE and has been prepared by him or on his behalf by Federal Express.

2. The shipper agrees that carriage is subject to terms and conditions of contract stated herein and those terms and conditions which are also stated in the most recent Federal Express Service Guide, which is available for inspection and incorporated into this contract by reference.

3. In tendering the shipment for carriage, THE SHIPPER WARRANTS that the shipment is packaged adequately to protect the enclosed goods and to insure safe transportation with ordinary care and handling, and that each package is appropriately labeled and is in good order (except as noted) for carriage as specified.

4. When the destination of the shipment is not within the Federal Express air terminal zone as listed in the most recent Federal Express Service Guide, Federal Express makes no commitment with respect to time of delivery of the shipment.

5. In the event of international carriage of any shipment hereunder, the rules relating to liability established by the Convention for the Unification of Certain Rules Relating to International Carriage by Air signed at Warsaw, Poland on October 12, 1929 shall apply to the carriage insofar as the same is governed thereby.

6. Federal Transportation Excise Tax. Pursuant to Section 4271 of the Internal Revenue Code, a 5% tax on air transportation portion of the service and the accessorial services related thereto is included within the basic rate.

7. DECLARED VALUE AND LIMITATION OF LIABILITY. THE LIABILITY OF FEDERAL EXPRESS IS LIMITED TO THE SUM OF \$100.00 unless a higher value is declared for carriage herein and a greater charge paid at the rate of 30¢ per \$100.00 value. The maximum higher declared value is \$5000.00. Shipments containing items of extraordinary value, including, but not limited to, drawings, paintings, sculptures, porcelain, ceramics, furs, fur clothing, fur trimmed clothing, jewelry, watches, gems, stones (precious or semi-precious, cut, or uncut), industrial, diamonds, costume jewelry, precious metals, gold, silver, (bullion, dust or precipitates), platinum (except as an integral part of electronic machinery), money, currency coins, trading stamps, stocks, bonds, cash letters (or their equivalent) and other extraordinary valuable items, are limited to a maximum declared value of \$500.00. When multiple packages are placed on a single airbill but the shipper has not specified the declared value of each individual package, the declared value for each individual package will be determined by dividing the total declared value on the airbill by the number of packages indicated on the airbill, subject to a \$100.00 minimum declared value per individual package. The liability of Federal Express is limited to the declared value of the shipment or the amount of loss or damage actually sustained, whichever is lower.

Federal Express is not liable for loss, damage, delay, mis-delivery or non-delivery not caused by its own negligence or any loss, damage, delay, mis-delivery or non-delivery caused by the act, default or omission of the shipper, consignee, or any other party who claims interest in the shipment, the nature of the shipment or any defect, characteristic or inherent vice thereof, violation by the shipper or consignee of any of the conditions of contract contained in this airbill or in the Federal Express Service Guide, including, but not limited to, improper or insufficient packing, securing,

marking or addressing, or failure to observe any of the rules relating to shipments not acceptable for transportation or shipments acceptable only under certain conditions; acts of God, perils of the air, public enemies, public authorities acting with actual or apparent authority, authority of law, acts or omissions of customs or quarantine officials, riots, strikes or other local disputes, civil commotions, hazards incident to a state of war, weather conditions or mechanical delay of the aircraft or acts or omissions of any person other than FEC, including compliance with delivery instructions from the shipper or consignee. FEC shall not be liable for the loss of articles loaded and sealed in packages by the shipper provided the seal is unbroken at the time of delivery and the package retains its basic integrity. **FEDERAL EXPRESS SHALL NOT BE LIABLE IN ANY EVENT FOR ANY SPECIAL, INCIDENTAL OR CONSEQUENTIAL DAMAGES, INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS OR INCOME WHETHER OR NOT FEDERAL EXPRESS HAD KNOWLEDGE THAT SUCH DAMAGES MIGHT BE INCURRED.**

8. CLAIMS. WRITTEN NOTICE OF LOSS DUE TO DAMAGE, SHORTAGE OR DELAY MUST BE REPORTED BY THE SHIPPER WITHIN 15 DAYS AFTER THE DELIVERY OF THE SHIPMENT. WRITTEN NOTICE OF LOSS DUE TO NON-DELIVERY MUST BE REPORTED BY THE SHIPPER WITHIN 180 DAYS AFTER ACCEPTANCE OF THE SHIPMENT OR CARRIAGE. Written notification will be considered to have been made if the shipper calls and notifies the Customer Services Department at 800/238-5355 (in Tennessee 800/542-5171) and as soon as practicable thereafter, files a written notification. Documentation of all claims other than overcharge claims must be submitted in writing to FEC within ninety (90) days after receipt of written notification. No claim for damage will be entertained until all transportation charges have been paid. The amount of a claim may not be deducted from the transportation charges. Receipt of the shipment by the consignee without written notification of damage on the delivery receipt shall be prima facie evidence that the shipment was delivered in good condition, except that in the case of claims for concealed damage which is not discovered at the time of delivery, the shipper shall notify FEC in writing as promptly as possible after the discovery thereof and in any event not later than 15 days from the date of delivery. The shipper must make the original shipping cartons and packing available for inspection by FEC. Claims for overcharges and refunds must be made in writing to FEC within twelve (12) months of the billing date. All claims must be filed by the shipper.

9. All shipments are subject to inspection by FEC, including but not limited to, opening the shipment. However, FEC is not obligated to perform such inspection.

10. C.O.D. services are not available and a C.O.D. shipment sent in error will be delivered as a normal pre-paid or collect shipment.

11. Federal Express carries no cargo liability insurance but maintains a separate fund for the satisfaction of cargo claims which may arise out of the carriage of cargo pursuant to the conditions of contract contained herein and in the most recent Federal Express Service Guide.

12. Notwithstanding the shipper's instructions to the contrary, the shipper shall be primarily liable for all costs and expenses related to the shipment of the package, and for costs incurred in either returning the shipment to the shipper or warehousing the shipment pending disposition.

13. Saturday Delivery: Recipient's phone number is required.



U.S. ENVIRONMENTAL PROTECTION AGENCY HWI Sample Management Office
P.O. Box 818, Alexandria, VA 22313-703 • 557-2490 • FTS 557-2490

INORGANICS TRAFFIC REPORT

Sample Number
MC 0983

① **Case Number:** _____
Sample Site Name/Code: _____

② **SAMPLE CONCENTRATION**

(Check One)

_____ Low Concentration

_____ Medium Concentration

③ **SAMPLE MATRIX**

(Check One)

_____ Water

_____ Soil/Sediment

④ **Ship To:** _____

Attn: _____

**Transfer
Ship To:** _____

⑤ **Sampling Office:** _____

Sampling Personnel: _____

(Name) _____

(Phone) _____

Sampling Date: _____

(Begin) _____ (End) _____

⑥ **Shipping Information:**

Name Of Carrier: _____

Date Shipped: _____

Airbill Number: _____

⑦ **Sample Description:**

(Check One)

_____ Surface Water

_____ Ground Water

_____ Leachate

_____ Mixed Media

_____ Solids

_____ Other

(specify) _____

⑧ **Mark Volume Level**

On Sample Bottle

Check Analysis required

_____ Task 1 & 2

_____ Task 3 Ammonia

Sulfide

Cyanide

MATCHES ORGANIC SAMPLE NO: _____

SMO COPY

GENERAL DIRECTIONS

1. Use only the materials provided to record sample information:

2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.

3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.

4. Where Inorganic Traffic Reports (ITR) must be mailed, be sure that all sheets are sent to the correct addressee.

5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the ITR's.

6. Relate any problems and/or questions concerning SMO procedures or the use of ITR's to the HWI Sample Management Office at (703) 557-2490.

ANALYSIS LABORATORY DIRECTIONS

1. Check condition of all samples and labels on arrival.

2. Verify that sample conforms to the information specified in Items 2 and 3 of the Inorganics Traffic Report. If there appears to be a discrepancy, immediately contact the HWI Sample Management Office.

3. Fill in information requested in Item 9 of the Inorganics Traffic Report and note comments regarding sample condition in Item 10.

4. Send the top sheet of the ITR (white copy) to the HWI Sample Management Office and retain the remaining yellow copy for your files.

5. Proceed with analysis, recording all pertinent comments on the Inorganics Data Sheets, QC Reports and/or in the narrative section of your Weekly Report.

0083



U.S. ENVIRONMENTAL PROTECTION AGENCY HWI Sample Management Office

P.O. Box 818, Alexandria, VA 22313-703/557-2490 • FTS/557-2490

Sample Number

MC 0983

INORGANICS TRAFFIC REPORT

① **Case Number:** _____
Sample Site Name/Code: _____

② **SAMPLE CONCENTRATION**

(Check One)

_____ Low Concentration
_____ Medium Concentration

③ **SAMPLE MATRIX**

(Check One)

_____ Water
_____ Soil/Sediment

④ **Ship To:**

Attn: _____

Transfer
Ship To: _____

⑤ **Sampling Office:** _____

Sampling Personnel: _____

(Name) _____

(Phone) _____

Sampling Date: _____

(Begin) _____ (End) _____

⑥ **Shipping Information:**

Name Of Carrier: _____

Date Shipped: _____

Airbill Number: _____

⑨ **ANALYSIS LAB:**

Recd by: _____

Date Recd: _____

⑦ **Sample Description:**

(Check One)

_____ Surface Water
_____ Ground Water
_____ Leachate
_____ Mixed Media
_____ Solids
_____ Other _____
(specify)

MATCHES ORGANIC SAMPLE NO. _____

⑧ **Mark Volume Level
On Sample Bottle**

Check Analysis required

_____ Task 1 & 2
_____ Task 3 Ammonia
Sulfide
Cyanide

⑩

**Sample Condition
On Receipt:**

(eg. broken, leakage, chain of custody, etc.)

LAB FILE COPY

GENERAL DIRECTIONS

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Inorganic Traffic Reports (ITR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the ITR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of ITR's to the HWI Sample Management Office at (703) 557-2490.

ANALYSIS LABORATORY DIRECTIONS

1. Check condition of all samples and labels on arrival.
2. Verify that sample conforms to the information specified in Items 2 and 3 of the Inorganics Traffic Report. If there appears to be a discrepancy, immediately contact the HWI Sample Management Office.
3. Fill in information requested in Item 9 of the Inorganics Traffic Report and note comments regarding sample condition in Item 10.
4. Send the top sheet of the ITR (white copy) to the HWI Sample Management Office and retain the remaining yellow copy for your files.
5. Proceed with analysis, recording all pertinent comments on the Inorganics Data Sheets, QC Reports and/or in the narrative section of your Weekly Report.



U.S. ENVIRONMENTAL PROTECTION AGENCY HWI Sample Management Office

P.O. Box 818, Alexandria, VA 22313-703/557-2490 • FTS/557-2490

Sample Number

MC 0939

INORGANICS TRAFFIC REPORT

① Case Number: 1806 SAS-6140
Sample Site Name/Code:

② SAMPLE CONCENTRATION
(Check One)

☐ Low Concentration
☐ Medium Concentration

③ SAMPLE MATRIX
(Check One)

☐ Water
☒ Soil/Sediment

④ Ship To:

VERSAR INC.
ORIGINAL (Red)

Attn: _____

Transfer
Ship To: _____

⑤ Sampling Office: DE

Sampling Personnel:

(Name) John A. Smith / D. H. Smith

(Phone) 215-647-7510

Sampling Date:

(Begin) 6/17/83 (End) 6/21/83

⑥ Shipping Information:

Name Of Carrier:

Date Shipped: 6-24-83

Airbill Number: 17770 178

⑦ Sample Description:
(Check One)

☐ Surface Water
☒ Ground Water
☐ Leachate
☐ Mixed Media
☒ Solids
☐ Other _____

(specify)

MATCHES ORGANIC SAMPLE NO. 6-3740

⑧ Mark Volume Level
On Sample Bottle

Check Analysis required

☒ Task 1 & 2
☒ Task 3 Ammonia
Sulfide
Cyanide

REGIONAL OFFICE FILE COPY

GENERAL DIRECTIONS

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Inorganic Traffic Reports (ITR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the ITR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of ITR's to the HWI Sample Management Office at (703) 557-2490.

SAMPLER DIRECTIONS

1. Note that a separate prenumbered Inorganics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1-8). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Inorganics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Sampling Coordinator.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. Fill in shipping information requested in Item 6. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
5. Send the first page of each ITR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
6. Insert the remaining two copies (white and yellow) of the ITR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.



U.S. ENVIRONMENTAL PROTECTION AGENCY HWI Sample Management Office

P.O. Box 818, Alexandria, VA 22313-703 / 557-2490 • FTS / 557-2490

INORGANICS TRAFFIC REPORT

Sample Number

MC 0982

① Case Number: 1836 SAS 6191
Sample Site Name/Code:

② SAMPLE CONCENTRATION

(Check One)

☒ Low Concentration☐ Medium Concentration

③ SAMPLE MATRIX

(Check One)

☐ Water☒ Soil/Sediment

④ Ship To:

VER SAR

ORIGINAL
(Red)

Attn: _____

Transfer
Ship To: _____

⑤ Sampling Office: IL

Sampling Personnel:

(Name) Dr. Neil Smith / D. H. Smith(Phone) 215-627-9510

Sampling Date:

(Begin) 6/24/83 (End) 6/24/83

⑥ Shipping Information:

Name Of Carrier:

Fed Ex - ExpressDate Shipped: 6-24-83Airbill Number: 191 204 113

⑦ Sample Description:

(Check One)

☐ Surface Water☐ Ground Water☐ Leachate☐ Mixed Media☒ Solids☐ Other _____

(specify)

MATCHES ORGANIC SAMPLE NO. 6-2741

⑧ Mark Volume Level
On Sample Bottle

Check Analysis required

☒ Task 1 & 2☒ Task 3 Ammonia

Sulfide

Cyanide

REGIONAL OFFICE FILE COPY

GENERAL DIRECTIONS

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Inorganic Traffic Reports (ITR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the ITR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of ITR's to the HWI Sample Management Office at (703) 557-2490.

SAMPLER DIRECTIONS

1. Note that a separate prenumbered Inorganics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1-8). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Inorganics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Sampling Coordinator.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. Fill in shipping information requested in Item 6. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
5. Send the first page of each ITR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
6. Insert the remaining two copies (white and yellow) of the ITR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.



U.S. ENVIRONMENTAL PROTECTION AGENCY HWI Sample Management Office

P.O. Box 818, Alexandria, VA 22313-703 / 557-2490 • FTS / 557-2490

Sample Number

MC 0984

INORGANICS TRAFFIC REPORT

① Case Number: 1226 SAS 6191
Sample Site Name/Code:

01-02

② SAMPLE CONCENTRATION

✓ (Check One)
____ Low Concentration
____ Medium Concentration

③ SAMPLE MATRIX (Check One)

____ Water
✓ Soil/Sediment

④ Ship To: VERSA INC.

Attn: ORIGINAL (Red)

Transfer
Ship To:

⑤ Sampling Office: FT

Sampling Personnel:

(Name) Carl A. Smith / J. H. Smith

(Phone) 215-147-1510

Sampling Date:

(Begin) 6/24/83 (End) 6/24/83

⑥ Shipping Information:

Name Of Carrier:

Date Shipped: 6-24-83

Airbill Number: 1915245-112

⑦ Sample Description:

(Check One)

____ Surface Water
____ Ground Water
____ Leachate
____ Mixed Media
✓ Solids
____ Other _____

(specify)

MATCHES ORGANIC SAMPLE NO. C-272

⑧ Mark Volume Level
On Sample Bottle

Check Analysis required

✓ Task 1 & 2
✓ Task 3 Ammonia
Sulfide
Cyanide

REGIONAL OFFICE FILE COPY

GENERAL DIRECTIONS

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Inorganic Traffic Reports (ITR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the ITR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of ITR's to the HWI Sample Management Office at (703) 557-2490.

SAMPLER DIRECTIONS

1. Note that a separate prenumbered Inorganics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1-8). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Inorganics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Sampling Coordinator.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. Fill in shipping information requested in Item 6. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
5. Send the first page of each ITR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
6. Insert the remaining two copies (white and yellow) of the ITR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.

GENERAL DIRECTIONS

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Inorganic Traffic Reports (ITR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the ITR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of ITR's to the HWI Sample Management Office at (703) 557-2490.

SAMPLER DIRECTIONS

1. Note that a separate prenumbered Inorganics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1-8). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Inorganics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Sampling Coordinator.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. Fill in shipping information requested in Item 6. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
5. Send the first page of each ITR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
6. Insert the remaining two copies (white and yellow) of the ITR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.



U.S. ENVIRONMENTAL PROTECTION AGENCY HWI Sample Management Office

P.O. Box 816, Alexandria, VA 22313-703/557-2490 • FTS/557-2490

Sample Number

ML 1002

INORGANICS TRAFFIC REPORT

① Case Number: 1836-5056190

Sample Site Name/Code:

m-02

② SAMPLE CONCENTRATION

(Check One)

☒ Low Concentration

☐ Medium Concentration

③ SAMPLE MATRIX

(Check One)

☐ Water

☒ Soil/Sediment

④ Ship To:

VERSAE INC.

ORIGINAL
(Red)

Attn: _____

Transfer

Ship To: _____

⑤ Sampling Office: ML

Sampling Personnel:

(Name) M. J. ...

(Phone) 202-241-7510

Sampling Date:

(Begin) 6/21/83 (End) 6/21/83

⑥ Shipping Information:

Name Of Carrier:

Fed Ex

Date Shipped: 6-24-83

Airbill Number: 177 206-178

⑦ Sample Description:

(Check One)

☐ Surface Water

☐ Ground Water

☐ Leachate

☐ Mixed Media

☐ Solids

☐ Other

(specify)

MATCHES ORGANIC SAMPLE NO. 6274

⑧ Mark Volume Level

On Sample Bottle

Check Analysis required

☒ Task 1 & 2

☒ Task 3 Ammonia

Sulfide

Cyanide

REGIONAL OFFICE FILE COPY

GENERAL DIRECTIONS

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Inorganic Traffic Reports (ITR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the ITR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of ITR's to the HWI Sample Management Office at (703) 557-2490.

SAMPLER DIRECTIONS

1. Note that a separate prenumbered Inorganics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1-8). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Inorganics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Sampling Coordinator.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. Fill in shipping information requested in Item 6. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
5. Send the first page of each ITR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
6. Insert the remaining two copies (white and yellow) of the ITR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.



U.S. ENVIRONMENTAL PROTECTION AGENCY HWI Sample Management Office

P.O. Box 818, Alexandria, VA 22313-703 / 557-2490 • FTS / 557-2490

INORGANICS TRAFFIC REPORT

Sample Number

MC 1003

① Case Number: 1836 SAS#6194

Sample Site Name/Code:

MC 1003
MC 1003
MC 1003

② SAMPLE CONCENTRATION

(Check One)

☒ Low Concentration
☐ Medium Concentration

③ SAMPLE MATRIX

(Check One)

☐ Water
☒ Soil/Sediment

④ Ship To:

USCASA INCORIGINAL
(Red)

Attn: _____

Transfer
Ship To: _____⑤ Sampling Office: DE

Sampling Personnel:

(Name) Theresa J. Smith / J. Smith(Phone) 212-627-9310

Sampling Date:

(Begin) 4/1/82 (End) 4/1/82

⑥ Shipping Information:

Name Of Carrier:

Federal ExpressDate Shipped: 6-24-83Airbill Number: 177 24 182

⑦ Sample Description:

(Check One)

☐ Surface Water
☐ Ground Water
☐ Leachate
☐ Mixed Media
☒ Solids
☐ Other _____

(specify)

⑧ Mark Volume Level

On Sample Bottle

Check Analysis required

☒ Task 1 & 2
☒ Task 3 Ammonia
Sulfide
CyanideMATCHES ORGANIC SAMPLE NO. (1836)

REGIONAL OFFICE FILE COPY

GENERAL DIRECTIONS

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Inorganic Traffic Reports (ITR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the ITR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of ITR's to the HWI Sample Management Office at (703) 557-2490.

SAMPLER DIRECTIONS

1. Note that a separate prenumbered Inorganics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1-8). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Inorganics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Sampling Coordinator.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. Fill in shipping information requested in Item 6. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
5. Send the first page of each ITR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
6. Insert the remaining two copies (white and yellow) of the ITR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.



U.S. ENVIRONMENTAL PROTECTION AGENCY HWI Sample Management Office

P.O. Box 818, Alexandria, VA 22313-703/557-2490 • FTS/557-2490

INORGANICS TRAFFIC REPORT

Sample Number

MC 1004

① Case Number: 1736 AS-0191

Sample Site Name/Code:

M-02

② SAMPLE CONCENTRATION

(Check One)

☒ Low Concentration

☐ Medium Concentration

③ SAMPLE MATRIX

(Check One)

☐ Water

☒ Soil/Sediment

④ Ship To:

Attn: _____

Transfer

Ship To: _____

ORIGINAL
(Red)

⑤ Sampling Office: NE

Sampling Personnel:

(Name) M. Dolan

(Phone) 215/687-9510

Sampling Date:

(Begin) 10-24-83 (End) 10-24-83

⑥ Shipping Information:

Name Of Carrier:

Federal Express

Date Shipped: 10-24-83

Airbill Number: 147 261143

⑦ Sample Description:

(Check One)

☐ Surface Water

☐ Ground Water

☐ Leachate

☐ Mixed Media

☐ Solids

☒ Other

BLANK
(specify)

⑧ Mark Volume Level

On Sample Bottle

Check Analysis required

☒ Task 1 & 2

☒ Task 3 Ammonia

Sulfide

Cyanide

MATCHES ORGANIC SAMPLE NO. 1546

REGIONAL OFFICE FILE COPY

GENERAL DIRECTIONS

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Inorganic Traffic Reports (ITR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the ITR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of ITR's to the HWI Sample Management Office at (703) 557-2490.

SAMPLER DIRECTIONS

1. Note that a separate prenumbered Inorganics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1-8). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Inorganics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Sampling Coordinator.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. Fill in shipping information requested in Item 6. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
5. Send the first page of each ITR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
6. Insert the remaining two copies (white and yellow) of the ITR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.



U.S. ENVIRONMENTAL PROTECTION AGENCY HWI Sample Management Office

P.O. Box 818, Alexandria, VA 22313-703/557-2490 • FTS/557-2490

Sample Number

MC 1208

INORGANICS TRAFFIC REPORT

① Case Number: 1550-15-1191

Sample Site Name/Code:

02

② SAMPLE CONCENTRATION

(Check One)

1 Low Concentration
____ Medium Concentration

③ SAMPLE MATRIX

(Check One)

____ Water
X Soil/Sediment

④ Ship To:

VERSAR INC
6021 ELECTRA DRIVE
SPRINGFIELD, MA 01104
ORIGINAL (Red)

Attn: JANET Beckman

Transfer
Ship To:

⑤ Sampling Office: MD

Sampling Personnel:

(Name) John A. Beckman / D. Beckman

(Phone) 202-462-9212

Sampling Date:

(Begin) 6/21/83 (End) 6/21/83

⑥ Shipping Information:

Name Of Carrier:

Date Shipped: 6-24-83

Airbill Number: 1917201193

⑦ Sample Description:

(Check One)

____ Surface Water
____ Ground Water
____ Leachate
____ Mixed Media
X Solids
____ Other _____

(specify)

MATCHES ORGANIC SAMPLE NO. 13705

⑧ Mark Volume Level
On Sample Bottle

Check Analysis required

____ Task 1 & 2
X Task 3 Ammonia
Sulfide
Cyanide

GENERAL DIRECTIONS

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Inorganic Traffic Reports (ITR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the ITR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of ITR's to the HWI Sample Management Office at (703) 557-2490.

SAMPLER DIRECTIONS

1. Note that a separate prenumbered Inorganics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1-8). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Inorganics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Sampling Coordinator.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. Fill in shipping information requested in Item 6. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
5. Send the first page of each ITR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
6. Insert the remaining two copies (white and yellow) of the ITR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.



U.S. ENVIRONMENTAL PROTECTION AGENCY HWI Sample Management Office

P.O. Box 818, Alexandria, VA 22313-703 / 557-2490 • FTS / 557-2490

INORGANICS TRAFFIC REPORT

Sample Number

MC 1209

① Case Number: 1836 AD-610

Sample Site Name/Code:

m 202

② SAMPLE CONCENTRATION

(Check One)

☒ Low Concentration

☐ Medium Concentration

③ SAMPLE MATRIX

(Check One)

☐ Water

☒ Soil/Sediment

④ Ship To:

VERSAK

ORIGINAL
(Red)

Attn:

Transfer

Ship To:

⑤ Sampling Office: ☐

Sampling Personnel:

(Name) D. K. K. / D. K. K.

(Phone) 202-741-9320

Sampling Date:

(Begin) 6/21/83 (End) 6/21/83

⑥ Shipping Information:

Name Of Carrier:

Exelco Express

Date Shipped: 6/24/83

Airbill Number: 107250172

⑦ Sample Description:

(Check One)

☐ Surface Water

☐ Ground Water

☐ Leachate

☐ Mixed Media

☐ Solids

☐ Other

(specify)

⑧ Mark Volume Level

On Sample Bottle

Check Analysis required

☒ Task 1 & 2

☒ Task 3 Ammonia

Sulfide

Cyanide

MATCHES ORGANIC SAMPLE NO. 5766

REGIONAL OFFICE FILE COPY

GENERAL DIRECTIONS

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Inorganic Traffic Reports (ITR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the ITR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of ITR's to the HWI Sample Management Office at (703) 557-2490.

SAMPLER DIRECTIONS

1. Note that a separate prenumbered Inorganics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1-8). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Inorganics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Sampling Coordinator.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. Fill in shipping information requested in Item 6. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
5. Send the first page of each ITR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
6. Insert the remaining two copies (white and yellow) of the ITR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.



U.S. ENVIRONMENTAL PROTECTION AGENCY HWI Sample Management Office

P.O. Box 818, Alexandria, VA 22313-703/557-2490 FTS/557-2490

Sample Number

MC 1210

INORGANICS TRAFFIC REPORT

① Case Number: 1856 8456 6196
Sample Site Name/Code: _____

② SAMPLE CONCENTRATION
(Check One)

☐ Low Concentration
☐ Medium Concentration

③ SAMPLE MATRIX
(Check One)

☐ Water
☒ Soil/Sediment

④ Ship To:

VERSAK INC

Attn: _____

Transfer
Ship To: _____

ORIGINAL
(Red)

⑤ Sampling Office: 11

Sampling Personnel: _____

(Name) James H. / J. H. Smith

(Phone) 703-557-2490

Sampling Date: _____

(Begin) 6/21/83 (End) 6/21/83

⑥ Shipping Information:

Name Of Carrier: _____

Date Shipped: 6-29-83

Airbill Number: 177-201-173

⑦ Sample Description:

(Check One)

☐ Surface Water
☐ Ground Water
☐ Leachate
☐ Mixed Media
☒ Solids
☐ Other _____

(specify)

⑧ Mark Volume Level

On Sample Bottle

Check Analysis required

☐ Task 1 & 2
☒ Task 3 Ammonia
Sulfide
Cyanide

MATCHES ORGANIC SAMPLE NO. 6-7176

REGIONAL OFFICE FILE COPY

GENERAL DIRECTIONS

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Inorganic Traffic Reports (ITR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the ITR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of ITR's to the HWI Sample Management Office at (703) 557-2490.

SAMPLER DIRECTIONS

1. Note that a separate prenumbered Inorganics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1-8). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Inorganics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Sampling Coordinator.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. Fill in shipping information requested in Item 6. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
5. Send the first page of each ITR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
6. Insert the remaining two copies (white and yellow) of the ITR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.



U.S. ENVIRONMENTAL PROTECTION AGENCY HWI Sample Management Office

P.O. Box 818, Alexandria, VA 22313-703/557-2490 • FTS/557-2490

INORGANICS TRAFFIC REPORT

Sample Number

MC 1211

① Case Number: 1836 SWS 60941

Sample Site Name/Code:

1836-2

② SAMPLE CONCENTRATION

(Check One)

☒ Low Concentration
☐ Medium Concentration

③ SAMPLE MATRIX

(Check One)

☐ Water
☒ Soil/Sediment

④ Ship To:

VERBAC INC

Attn: _____

Transfer
Ship To: _____

ORIGINAL
(Red)

⑤ Sampling Office: 705

Sampling Personnel:

(Name) 1836-2 SWS 60941

(Phone) 212-647-9310

Sampling Date:

(Begin) 5/31/83 (End) 6/2/83

⑥ Shipping Information:

Name Of Carrier:

Federal Express

Date Shipped: 6-14-83

Airbill Number: 147701143

⑦ Sample Description:

(Check One)

☐ Surface Water
☐ Ground Water
☐ Leachate
☐ Mixed Media
☒ Solids
☐ Other _____

(specify)

⑧ Mark Volume Level

On Sample Bottle

Check Analysis required

☐ Task 1 & 2
☒ Task 3 Ammonia
Sulfide
Cyanide

MATCHES ORGANIC SAMPLE NO. 63727

REGIONAL OFFICE FILE COPY

GENERAL DIRECTIONS

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Inorganic Traffic Reports (ITR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the ITR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of ITR's to the HWI Sample Management Office at (703) 557-2490.

SAMPLER DIRECTIONS

1. Note that a separate prenumbered Inorganics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1-8). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Inorganics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Sampling Coordinator.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. Fill in shipping information requested in Item 6. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
5. Send the first page of each ITR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
6. Insert the remaining two copies (white and yellow) of the ITR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.



U.S. ENVIRONMENTAL PROTECTION AGENCY HWI Sample Management Office

P.O. Box 818, Alexandria, VA 22313-703/557-2490 • FTS/557-2490

Sample Number

MC 1212

INORGANICS TRAFFIC REPORT

① Case Number: 1536 SANF691

Sample Site Name/Code: _____

② SAMPLE CONCENTRATION

(Check One)

☒ Low Concentration

☐ Medium Concentration

③ SAMPLE MATRIX

(Check One)

☐ Water

☒ Soil/Sediment

④ Ship To:

VORSAF
ORIGINAL
(Red) Ink

Attn: _____

Transfer
Ship To: _____

⑤ Sampling Office: _____

Sampling Personnel: _____

(Name): _____

(Phone): 813-687-0851

Sampling Date: _____

(Begin): 5/2/82 (End): 6/2/82

⑥ Shipping Information:

Name Of Carrier: _____

Fed Ex

Date Shipped: 6-4-82

Airbill Number: 147-211 142

⑦ Sample Description:

(Check One)

☐ Surface Water

☐ Ground Water

☐ Leachate

☐ Mixed Media

☒ Solids

☐ Other _____

(specify)

⑧ Mark Volume Level

On Sample Bottle

Check Analysis required

☒ Task 1 & 2

☐ Task 3 Ammonia

Sulfide

Cyanide

MATCHES ORGANIC SAMPLE NO. 7378

REGIONAL OFFICE FILE COPY

GENERAL DIRECTIONS

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Inorganic Traffic Reports (ITR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the ITR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of ITR's to the HWI Sample Management Office at (703) 557-2490.

SAMPLER DIRECTIONS

1. Note that a separate prenumbered Inorganics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1-8). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Inorganics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Sampling Coordinator.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. Fill in shipping information requested in Item 6. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
5. Send the first page of each ITR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
6. Insert the remaining two copies (white and yellow) of the ITR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.



U.S. ENVIRONMENTAL PROTECTION AGENCY HWI Sample Management Office

P.O. Box 818, Alexandria, VA 22313-703 / 557-2490 • FTS / 557-2490

INORGANICS TRAFFIC REPORT

Sample Number

MC 1213

① Case Number: 18316 SAT-019
Sample Site Name/Code:
02-102**② SAMPLE CONCENTRATION**

(Check One)
☒ Low Concentration
☐ Medium Concentration

③ SAMPLE MATRIX

(Check One)
☐ Water
☐ Soil/Sediment

④ Ship To:VERSA INC**Attn:** _____**Transfer
Ship To:** _____**ORIGINAL
(Red)****⑤ Sampling Office:** TD**Sampling Personnel:**(Name) Mr. [illegible](Phone) 202-1047-9510**Sampling Date:**(Begin) 4/30/82 (End) 5/1/82**⑥ Shipping Information:****Name Of Carrier:**FedEx**Date Shipped:** 5-1-82**Airbill Number:** 147-001012**⑦ Sample Description:**

(Check One)

☐ Surface Water
☐ Ground Water
☐ Leachate
☐ Mixed Media
☒ Solids
☐ Other _____

(specify)

MATCHES ORGANIC SAMPLE NO. 18316**⑧ Mark Volume Level
On Sample Bottle**

Check Analysis required

☒ Task 1 & 2
☒ Task 3 Ammonia
Sulfide
Cyanide

GENERAL DIRECTIONS

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Inorganic Traffic Reports (ITR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the ITR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of ITR's to the HWI Sample Management Office at (703) 557-2490.

SAMPLER DIRECTIONS

1. Note that a separate prenumbered Inorganics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1-8). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Inorganics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Sampling Coordinator.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. Fill in shipping information requested in Item 6. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
5. Send the first page of each ITR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
6. Insert the remaining two copies (white and yellow) of the ITR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.

(Provide at least two copies to the airline)

SHIPPER'S CERTIFICATION FOR RESTRICTED ARTICLES
(excluding radioactive materials)

Two completed and signed copies of this certification shall be handed to the carrier. (Use block letters)

WARNING: Failure to comply in all respects with the applicable regulations of the Department of Transportation, 49-CFR, CAB 82 and, for international shipments, the IATA Restricted Articles Regulations may be a breach of the applicable law, subject to legal penalties. This certification shall in no circumstance be signed by an IATA Cargo Agent or a consolidator for international shipments.

This shipment is within the limitations prescribed for: (mark one)

☐ passenger aircraft

☒ cargo-only aircraft

Number of Packages	Article Number (Int'l only See Section IV IATA RAR)	Proper Shipping Name of Articles as shown in Title 49 CFR, CAB 82 Tariff 6-D, and (for int'l shipments) the IATA Restricted Articles Regulations. Specify each article separately. Technical name must follow in parenthesis, the proper shipping name for N.O.S. items.	Class	IATA Packing Note No. Applied (int'l only)	Net Quantity per Package	Flash Point (closed cup) For Flammable Liquids	
						°C	°F
1	UN1325	FLAMMABLE Solid NOS			18oz. in 3 containers		

RECEIVED
OCT 10 1983
NUS CORPORATION
REGION III
SENT TO

Cargo-Only aircraft

Special Handling Information:

I hereby certify that the contents of this consignment are fully and accurately described above by Proper Shipping Name and are classified, packed, marked, labelled, and in proper condition for carriage by air according to applicable national governmental regulations, and for International Shipments, the current IATA Restricted Articles Regulations.

Name and full address of Shipper Envirodyne Engrs. 12161 LACKLAND RD. ST. LOUIS, Mo. 63146		Name and title of person signing Certification VERN A. LUKER SAMPLE CUSTODIAN ORIGINAL 314-454-6960	
Date 10-07-83		Signature of the Shipper (see WARNING above) Vern A. Luker	
Air Waybill No.* 226215754	Airport of Departure* STL	Airport of Destination* PNE	

*This box is optional for completion by issuing carrier.

(Provide at least two copies to the airline)

SHIPPER'S CERTIFICATION FOR RESTRICTED ARTICLES (excluding radioactive materials)

Two completed and signed copies of this certification shall be handed to the carrier. (Use block letters)

WARNING: Failure to comply in all respects with the applicable regulations of the Department of Transportation, 49-CFR, CAB 82 and, for international shipments, the IATA Restricted Articles Regulations may be a breach of the applicable law, subject to legal penalties. This certification shall in no circumstance be signed by an IATA Cargo Agent or a consolidator for international shipments.

This shipment is within the limitations prescribed for: (mark one)

☐ passenger aircraft

☒ cargo-only aircraft

Number of Packages	Article Number (Int'l only. See Section IV IATA RAR)	Proper Shipping Name of Articles as shown in Title 49 CFR, CAB 82 Tariff 6-D, and (for int'l shipments) the IATA Restricted Articles Regulations. Specify each article separately. Technical name must follow in parenthesis, the proper shipping name for N.O.S. items	Class	IATA Packing Note No. Applied (Int'l only)	Net Quantity per Package	Flash Point (closed cup) For Flammable Liquids	
						°C.	°F.
1	UN1325	Flammable Solid NOS			18oz. in 3 containers		

RECEIVED

OCT 10 1983

NUS CORPORATION
REGION III
SENT TO

CARGO-Only
aircraft

Special Handling Information:

I hereby certify that the contents of this consignment are fully and accurately described above by Proper Shipping Name and are classified, packed, marked, labelled and in proper condition for carriage by air according to applicable national governmental regulations, and for International Shipments, the current IATA Restricted Articles Regulations.

Name and full address of Shipper: Envirodyne Engrs 12161 LACKLAND Rd. ST. LOUIS, MO. 63146		Name and title of person signing Certification: Vern A. Luker Sample Custodian 314-439-6960	
Date: 10-07-83		Signature of the Shipper (see WARNING above): Vern A. Luker	
Air Waybill No.:	Airport of Departure:	Airport of Destination:	
226215754	STL	PNE	

*This box is optional for completion by issuing carrier.

SAMPLE SHIPPING/RECEIVING LOG

COPY

[illegible]

Site Leader: Please complete only the columns shaded at the bottom of this page.

SAMPLE SHIPPING/RECEIVING LOG

copy

CASE NO.	PROJECT NAME	EPA SITE NUMBER	EXTRN / ANAL. LAB	QC INFO.		MATRIX/CONC/ PROTOCOL			SAMPLE TRAFFIC REPORT NUMBER	DATE SHIPPED	EXPECTED ARRIVAL	DATE RECEIVED							
				BLANK	H ₂ O SOURCE	DUP.	MATCHES TR	ORG/ INOR.				LO MED HI	AGNIO / SOL/ MULTI	VA	ACID	B/N	PEST	TCD	I
SAS NO.	TDD NUMBER	SITE LEADER	CONTRACT NUMBER	MATRIX SPIKE	UNSPIKED TR	0.5/1/III													
1836	Amchem (cont)	M-02	Envirodyne			2,3,7,8-TCDD	Low	Sol.	M-02-04										
619C	8306-21	Shannon							M-02-05										
									M-02-06										
									M-02-07										
									M-02-08										
									M-02-09										
									M-02-10										
									M-02-12										
									M-02-13										
									M-02-14										
									M-02-14										
									M-02-15										
									M-02-16										

ORIGINAL
(Red)



3-10880

CHAIN OF CUSTODY RECORD

[illegible]

CHAIN OF CUSTODY RECORD

PROJ. NO.		PROJECT NAME				NO. OF CON- TAINERS	REMARKS										
SAMPLERS: (Signature)																	
STA. NO.	DATE	TIME	COMP.	GRAB	STATION LOCATION												
8306-20	6/12/83	11:50		X	Family - North Side	1	TR# C-3705 / Tag # 3-15583										
8306-21	6/12/83	11:20		X	Family - North Side	2	TR# C-3706 / Tag # 3-15714										
8306-22	6/12/83	11:25		X	Family - North Side	3	TR# C-3720 / Tag # 3-14594										
8306-23	6/12/83	12:12		X	Family - South Side	4	TR# C-3737 / Tag # 3-17517										
8306-24	6/12/83	12:41		X	Family - North Side	5	TR# C-3738 / Tag # 3-12086										
8306-25	6/12/83	13:04		X	Family - North Side	6	TR# C-3751 / Tag # 3-12092										
8306-26	6/12/83	13:29		X	Family - North Side	7	TR# C-3740 / Tag # 3-12092										
8306-27	6/12/83	13:36		X	Family - South Side	8	TR# C-3741 / Tag # 3-12096										
8306-28	6/12/83	13:55		X	Family - South Side	9	TR# C-3742 / Tag # 3-12099										
8306-29	6/12/83	14:35		X	Family - South Side	10	TR# C-3743 / Tag # 3-24055										
8306-30	6/12/83	14:41		X	Family - South Side	11	TR# C-3744 / Tag # 3-24064										
8306-31	6/12/83	17:12		X	Family - South Side	12	TR# C-3745 / Tag # 3-24062										
8306-32	6/12/83	18:00		X	TR# C-3746	13	TR# C-3746 / Tag # 3-24066										
Relinquished by: (Signature)						Date / Time		Received by: (Signature)				Date / Time		Received by: (Signature)			
Relinquished by: (Signature)						Date / Time		Received by: (Signature)				Date / Time		Received by: (Signature)			
Relinquished by: (Signature)						Date / Time		Received for Laboratory by: (Signature)				Date / Time		Remarks			

Distribution: Original Accompanies Shipment; Copy to Coordinator Field Files

Shipped via Federal Express
A/c # 147201132

3-10877

CHAIN OF CUSTODY RECORD

PROJ. NO.		PROJECT NAME				NO. OF CONTAINERS	REMARKS										
F3-8306-20		m-02															
SAMPLERS: (Signature)						1-quart jar											
Michael J. Halpin / David E. Hunk																	
STA. NO.	DATE	TIME	COMP.	GRAB	STATION LOCATION												
m-02-01	6/21/83	1050		X	Facility, North Side	2	2										
m-02-02	6/21/83	1120		X	Facility, North Side	2	2										
m-02-03	6/21/83	1145		X	Facility, North Side	2	2										
m-02-04	6/21/83	1212		X	Facility, South Side	2	2										
m-02-05	6/21/83	1244		X	Facility, North Side	2	2										
m-02-06	6/21/83	1309		X	Facility, North Side	2	2										
m-02-07	6/24/83	1329		X	Facility, North Side	2	2										
m-02-08	6/21/83	1336		X	Facility, South Side	2	2										
m-02-09	6/21/83	1555		X	Facility, South Side	2	2										
m-02-10	6/21/83	1635		X	Facility, South Side	2	2										
m-02-11	6/21/83	1651		X	Facility, South Side	2	2										
m-02-12	6/21/83	1715		X	Facility, South Side	2	2										

Relinquished by: (Signature)	Date / Time	Received by: (Signature)	Relinquished by: (Signature)	Date / Time	Received by: (Signature)
Timothy M. ...	6/21/83 1800	C. A. Shaloon			
Relinquished by: (Signature)	Date / Time	Received by: (Signature)	Relinquished by: (Signature)	Date / Time	Received by: (Signature)
Relinquished by: (Signature)	Date / Time	Received for Laboratory by: (Signature)	Date / Time	Remarks	
				Split samples transferred to FmC	

Distribution: Original Accompanies Shipment; Copy to Coordinator Field Files

3-10399

CHAIN OF CUSTODY RECORD

PROJ. NO.		PROJECT NAME					NO. OF CON- TAINERS	REMARKS									
F3-8306-20		m-02															
SAMPLERS: (Signature) <i>Don E. Himmelsch</i> <i>Michael J. Kalypinski</i>																	
STA. NO.	DATE	TIME	COMP.	GRAB	STATION LOCATION												
m-02-01	6/21/83	1040		X	Facility, North Side		1	1									
m-02-02	6/21/83	1111		X	Facility, Access Side		1	1									
m-02-03	6/21/83	1158		X	Facility, Access Side		1	1									
m-02-04	6/21/83	1208		X	Facility, South Side		1	1									
m-02-05	6/21/83	1237		X	Facility, Access Side		1	1									
m-02-06	6/21/83	1305		X	Facility, North Side		1	1									
m-02-07	6/21/83	1326 (12)		X	Facility, Access Side		1	1									
m-02-08	6/21/83	1523		X	Facility, South Side		1	1									
m-02-09	6/21/83	1549		X	Facility, South Side		1	1									
m-02-10	6/21/83	1630		X	Facility, South Side		1	1									
m-02-11	6/21/83	1648 (12)		X	Facility, South Side		1	1									
m-02-12	6/21/83	1717		X	Facility, South Side		1	1									

Relinquished by: (Signature) <i>Tom Allen</i>	Date / Time 6/21/83 1800	Received by: (Signature) <i>C.A. Shaheen</i>	Relinquished by: (Signature)	Date / Time	Received by: (Signature)
Relinquished by: (Signature)	Date / Time	Received by: (Signature)	Relinquished by: (Signature)	Date / Time	Received by: (Signature)
Relinquished by: (Signature)	Date / Time	Received for Laboratory by: (Signature)	Date / Time	Remarks Samples transferred to fmc	

Distribution: Original Accompanies Shipment; Copy to Coordinator Field Files

3-10398



U.S. ENVIRONMENTAL PROTECTION AGENCY HWI Sample Management Office
P.O. Box 813, Alexandria, Virginia 22313 703/557-2400 • FTS: 557 2493

ORGANICS TRAFFIC REPORT

Sample Number

6 3705

① Case Number:

1836 SAS# 6194

Sample Site Name/Code:

m-02

② SAMPLE CONCENTRATION

(Check One)

☒ Low Concentration
☐ Medium Concentration

③ SAMPLE MATRIX

(Check One)

☐ Water
☒ Soil/Sediment

④ Ship To:

MEAD Comp/chem
P.O. Box 12652
3705 Chapel Hill/Nelson Hwy
Research Triangle Park, NC 27709

Attn: Angie FR/e

Transfer

Ship To:

⑤ Regional Office: III

Sampling Personnel:

M. Nalinski/D. Hasselck

(Name)

45-687-9510

(Phone)

Sampling Date:

6/21/83

(Begin)

6/21/83

(End)

⑥ For each sample collected specify number of containers used and mark volume level on each bottle.

	Number of Containers	Approximate Total Volume
Water (Extractable)		
Water (VOA)		
Soil/Sediment	1	802
Water (Ext/VOA)		
Other		

⑦ Shipping Information

Federal Express

Name of Carrier

6-24-83

Date Shipped:

147201132

Airbill Number:

⑧ Sample Description

☐ Surface Water ☐ Mixed Media

☐ Ground Water ☒ Solids

☐ Leachate ☐ Other (specify) _____

⑨ Sample Location

m-02-01

⑩ Special Handling Instructions:

(e.g., safety precautions, hazardous nature)

ORIGINAL
(Red)

U.S. ENVIRONMENTAL PROTECTION AGENCY

Hazardous Waste Investigation

Sample Management Office

P.O. Box 818

Alexandria, Virginia 22313

Phone: (703) 557-2490/FTS-8-557-2490

General Directions

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Organic Traffic Reports (OTR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the OTR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of OTR's to the HWI Sample Management Office at (703) 557-2490.

Sampler Directions

1. Note that a separate prenumbered Organics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1-10). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Organics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Regional DPO.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. For samples containing especially hazardous substances, indicate any special handling instructions in the space provided in Item 10; and attach a separate tag bearing the appropriate SMO Sample ID number in addition to the label provided.
5. Fill in shipping information requested in Item 7. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
6. Send the first page of each OTR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
7. Insert the remaining two copies (white and yellow) of the OTR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.



ORGANICS TRAFFIC REPORT

① Case Number:

1936 SAS 60191

Sample Site Name/Code:

m-02

② SAMPLE CONCENTRATION

(Check One)

☒ Low Concentration
☐ Medium Concentration

③ SAMPLE MATRIX

(Check One)

☐ Water
☒ Soil/Sediment

④ Ship To:

Meach Comp/chem

Attn:

Transfer

Ship To:

⑤ Regional Office: III

Sampling Personnel:

M. A. O. / D. H. O. S. I. C. K.

(Name)

5-687-9514

(Phone)

Sampling Date:

6/21/83 6/21/83

(Begin)

(End)

⑥ For each sample collected specify number of containers used and mark volume level on each bottle.

	Number of Containers	Approximate Total Volume
Water (Extractable)		
Water (VOA)		
Soil/Sediment	1	8.82
Water (Ext/VOA)		
Other		

⑦ Shipping Information

Federal Express

Name of Carrier

6-24-83

Date Shipped:

147301132

Airbill Number:

⑧ Sample Description

☐ Surface Water ☐ Mixed Media

☐ Ground Water ☒ Solids

☐ Leachate ☐ Other (specify) _____

⑨ Sample Location

m-02-02

⑩ Special Handling Instructions:

(e.g., safety precautions, hazardous nature)

ORIGINAL
(Red)

U.S. ENVIRONMENTAL PROTECTION AGENCY
Hazardous Waste Investigation
Sample Management Office
P.O. Box 818
Alexandria, Virginia 22313
Phone: (703) 557-2490/FTS-8-557-2490

General Directions

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Organic Traffic Reports (OTR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the OTR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of OTR's to the HWI Sample Management Office at (703) 557-2490.

Sampler Directions

1. Note that a separate prenumbered Organics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1 - 10). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Organics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Regional DPO.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. For samples containing especially hazardous substances, indicate any special handling instructions in the space provided in Item 10, and attach a separate tag bearing the appropriate SMO Sample ID number in addition to the label provided.
5. Fill in shipping information requested in Item 7. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
6. Send the first page of each OTR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
7. Insert the remaining two copies (white and yellow) of the OTR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.

U.S. ENVIRONMENTAL PROTECTION AGENCY
Hazardous Waste Investigation
Sample Management Office
P.O. Box 818
Alexandria, Virginia 22313
Phone: (703) 557-2490/FTS-8-557-2490

General Directions

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Organic Traffic Reports (OTR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the OTR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of OTR's to the HWI Sample Management Office at (703) 557-2490.

Sampler Directions

1. Note that a separate prenumbered Organics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1-10). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Organics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Regional DPO.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. For samples containing especially hazardous substances, indicate any special handling instructions in the space provided in Item 10, and attach a separate tag bearing the appropriate SMO Sample ID number in addition to the label provided.
5. Fill in shipping information requested in Item 7. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
6. Send the first page of each OTR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
7. Insert the remaining two copies (white and yellow) of the OTR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.



ORGANICS TRAFFIC REPORT

① Case Number:

1836 SAS 1019C

Sample Site Name/Code:

12-02

② SAMPLE CONCENTRATION

(Check One)

☒ Low Concentration
☐ Medium Concentration

③ SAMPLE MATRIX

(Check One)

☐ Water
☒ Soil/Sediment

④ Ship To:

MAAD Comp/Chem

Attn:

Transfer

Ship To:

⑤ Regional Office: III

Sampling Personnel:

12-National/1019C/D. HARRIS

(Name)

5-687-9518

(Phone)

Sampling Date:

(Begin)

(End)

⑥ For each sample collected specify number of containers used and mark volume level on each bottle.

	Number of Containers	Approximate Total Volume
Water (Extractable)		
Water (VOA)		
Soil/Sediment	12	5.02
Water (Ext/VOA)		
Other		

⑦ Shipping Information

Federal Express

Name of Carrier

6-24-85

Date Shipped:

147701122

Airbill Number:

⑧ Sample Description

☐ Surface Water ☐ Mixed Media
☐ Ground Water ☒ Solids
☐ Leachate ☐ Other (specify) _____

⑨ Sample Location

ORIGINAL (Recd)

⑩ Special Handling Instructions:

(e.g., safety precautions, hazardous nature)

U.S. ENVIRONMENTAL PROTECTION AGENCY
Hazardous Waste Investigation
Sample Management Office
P.O. Box 818
Alexandria, Virginia 22313
Phone: (703) 557-2490/FTS-8-557-2490

General Directions

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Organic Traffic Reports (OTR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the OTR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of OTR's to the HWI Sample Management Office at (703) 557-2490.

Sampler Directions

1. Note that a separate prenumbered Organics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1 - 10). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Organics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Regional DPO.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. For samples containing especially hazardous substances, indicate any special handling instructions in the space provided in Item 10, and attach a separate tag bearing the appropriate SMO Sample ID number in addition to the label provided.
5. Fill in shipping information requested in Item 7. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
6. Send the first page of each OTR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
7. Insert the remaining two copies (white and yellow) of the OTR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.



U.S. ENVIRONMENTAL PROTECTION AGENCY HWI Sample Management Office
P.O. Box 818, Alexandria, Virginia 22313-7018 • TIS 557-2490 • FTS 557-2490

Sample Number

C 3738

ORGANICS TRAFFIC REPORT

① Case Number:

1836 SAS # 6191

Sample Site Name/Code:

11-02

② SAMPLE CONCENTRATION

(Check One)

☒ Low Concentration
☐ Medium Concentration

③ SAMPLE MATRIX

(Check One)

☐ Water
☒ Soil/Sediment

④ Ship To:

MOAD Comp/Chem

Attn:

Transfer

Ship To:

⑤ Regional Office:

Sampling Personnel:

M. Nelson / J. H. H. K.

(Name)

6-637-7310

(Phone)

Sampling Date:

6/21/82 6/21/82

(Begin)

(End)

⑥ For each sample collected specify number of containers used and mark volume level on each bottle.

	Number of Containers	Approximate Total Volume
Water (Extractable)		
Water (VOA)		
Soil/Sediment	1	5 ml
Water (Ext/VOA)		
Other		

⑦ Shipping Information

Federal Express

Name of Carrier

6-24-5

Date Shipped:

147 201 132

Airbill Number:

⑧ Sample Description

☐ Surface Water ☐ Mixed Media

☐ Ground Water ☒ Solids

☐ Leachate ☐ Other (specify) _____

⑨ Sample Location

ORIGINAL
(Red)

⑩ Special Handling Instructions:

(e.g., safety precautions, hazardous nature)

U.S. ENVIRONMENTAL PROTECTION AGENCY

Hazardous Waste Investigation

Sample Management Office

P.O. Box 818

Alexandria, Virginia 22313

Phone: (703) 557-2490/FTS-8-557-2490

General Directions

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Organic Traffic Reports (OTR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the OTR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of OTR's to the HWI Sample Management Office at (703) 557-2490.

Sampler Directions

1. Note that a separate prenumbered Organics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1-10). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Organics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Regional DPO.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. For samples containing especially hazardous substances, indicate any special handling instructions in the space provided in Item 10, and attach a separate tag bearing the appropriate SMO Sample ID number in addition to the label provided.
5. Fill in shipping information requested in Item 7. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
6. Send the first page of each OTR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
7. Insert the remaining two copies (white and yellow) of the OTR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.



ORGANICS TRAFFIC REPORT

① Case Number:

1836 SAS#644

Sample Site Name/Code:

m-02

② SAMPLE CONCENTRATION

(Check One)

☒ Low Concentration
☐ Medium Concentration

③ SAMPLE MATRIX

(Check One)

☐ Water
☒ Soil/Sediment

④ Ship To:

MRAD Comp/Chn

Attn:

Transfer

Ship To:

⑤ Regional Office: IV

Sampling Personnel:

M. A. G. / D. H. / K.

(Name)

687-7510

(Phone)

Sampling Date:

6/7/87

(Begin) (End)

⑥ For each sample collected specify number of containers used and mark volume level on each bottle.

	Number of Containers	Approximate Total Volume
--	----------------------	--------------------------

Water (Extractable)		
---------------------	--	--

Water (VOA)		
-------------	--	--

Soil/Sediment	1.2	802
---------------	-----	-----

Water (Ext/VOA)		
-----------------	--	--

Other		
-------	--	--

⑦ Shipping Information

Federal Express

Name of Carrier

6-24-87

Date Shipped:

147-201-132

Airbill Number:

⑧ Sample Description

☐ Surface Water ☐ Mixed Media

☐ Ground Water ☒ Solids

☐ Leachate ☐ Other (specify) _____

⑨ Sample Location

m-02-06

ORIGINAL (Red)

⑩ Special Handling Instructions:

(e.g., safety precautions, hazardous nature)

U.S. ENVIRONMENTAL PROTECTION AGENCY
Hazardous Waste Investigation
Sample Management Office
P.O. Box 818
Alexandria, Virginia 22313
Phone: (703) 557-2490/FTS-8-557-2490

General Directions

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Organic Traffic Reports (OTR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the OTR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of OTR's to the HWI Sample Management Office at (703) 557-2490.

Sampler Directions

1. Note that a separate prenumbered Organics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1 - 10). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Organics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Regional DPO.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. For samples containing especially hazardous substances, indicate any special handling instructions in the space provided in Item 10, and attach a separate tag bearing the appropriate SMO Sample ID number in addition to the label provided.
5. Fill in shipping information requested in Item 7. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
6. Send the first page of each OTR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
7. Insert the remaining two copies (white and yellow) of the OTR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.



ORGANICS TRAFFIC REPORT

① Case Number:

1830 SPS-6196

Sample Site Name/Code:

m-42

② SAMPLE CONCENTRATION

(Check One)

☒ Low Concentration
☐ Medium Concentration

③ SAMPLE MATRIX

(Check One)

☐ Water
☒ Soil/Sediment

④ Ship To:

MOO Corp/Cor

Attn:

Transfer

Ship To:

⑤ Regional Office: III

Sampling Personnel:

MINDY L. (F.) HAWICK

(Name)

15-647-7510

(Phone)

Sampling Date:

6/21/82 6/21/82

(Begin)

(End)

⑥ For each sample collected specify number of containers used and mark volume level on each bottle.

	Number of Containers	Approximate Total Volume
Water (Extractable)		
Water (VOA)		
Soil/Sediment	1	8 c2
Water (Ext/VOA)		
Other		

⑦ Shipping Information

Federal Express

Name of Carrier

6-24-83

Date Shipped:

147 20 132

Airbill Number:

⑧ Sample Description

☐ Surface Water ☐ Mixed Media
☐ Ground Water ☒ Solids
☐ Leachate ☐ Other (specify) _____

⑨ Sample Location

ORIGINAL
(Red)

⑩ Special Handling Instructions:

(e.g., safety precautions, hazardous nature)

U.S. ENVIRONMENTAL PROTECTION AGENCY

Hazardous Waste Investigation

Sample Management Office

P.O. Box 818

Alexandria, Virginia 22313

Phone: (703) 557-2490/FTS-8-557-2490

General Directions

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil; and make sure all information is transferred to carbon pages.
4. Where Organic Traffic Reports (OTR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the OTR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of OTR's to the HWI Sample Management Office at (703) 557-2490.

Sampler Directions

1. Note that a separate prenumbered Organics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1 - 10). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Organics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Regional DPO.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. For samples containing especially hazardous substances, indicate any special handling instructions in the space provided in Item 10, and attach a separate tag bearing the appropriate SMO Sample ID number in addition to the label provided.
5. Fill in shipping information requested in Item 7. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
6. Send the first page of each OTR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
7. Insert the remaining two copies (white and yellow) of the OTR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.



U.S. ENVIRONMENTAL PROTECTION AGENCY HWI Sample Management Office
P.O. Box 818, Alexandria, Virginia 22313-7037/557-2490 • FTS/557-2490

Sample Number

3741

ORGANICS TRAFFIC REPORT

① Case Number:

1836 SAS # 6192

Sample Site Name/Code:

M-02

② SAMPLE CONCENTRATION

(Check One)

☒ Low Concentration
☐ Medium Concentration

③ SAMPLE MATRIX

(Check One)

☐ Water
☒ Soil/Sediment

④ Ship To:

Head Comp/Chem

Attn:

Transfer

Ship To:

⑤ Regional Office: III

Sampling Personnel:

M. J. D. H. S. C.
(Name)

687-9510
(Phone)

Sampling Date:

6/21/82 6/21/82
(Begin) (End)

⑥ For each sample collected specify number of containers used and mark volume level on each bottle.

	Number of Containers	Approximate Total Volume
Water (Extractable)		
Water (VOA)		
Soil/Sediment	4	8 c2
Water (Ext/VOA)		
Other		

⑦ Shipping Information

Federal Express

Name of Carrier

6-24-83

Date Shipped:

147-201-182

Airbill Number:

⑧ Sample Description

☐ Surface Water ☐ Mixed Media
☐ Ground Water ☒ Solids
☐ Leachate ☐ Other (specify) _____

⑨ Sample Location

M-02-09

⑩ Special Handling Instructions:

(e.g., safety precautions, hazardous nature)

ORIGINAL
(Red)

U.S. ENVIRONMENTAL PROTECTION AGENCY

Hazardous Waste Investigation

Sample Management Office

P.O. Box 818

Alexandria, Virginia 22313

Phone: (703) 557-2490/FTS-8-557-2490

General Directions

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Organic Traffic Reports (OTR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the OTR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of OTR's to the HWI Sample Management Office at (703) 557-2490.

Sampler Directions

1. Note that a separate prenumbered Organics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1-10). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Organics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Regional DPO.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. For samples containing especially hazardous substances, indicate any special handling instructions in the space provided in Item 10, and attach a separate tag bearing the appropriate SMO Sample ID number in addition to the label provided.
5. Fill in shipping information requested in Item 7. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
6. Send the first page of each OTR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
7. Insert the remaining two copies (white and yellow) of the OTR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.

ORGANICS TRAFFIC REPORT

3712

① Case Number: <u>1836 SAS-619A</u>		② SAMPLE CONCENTRATION (Check One) <input checked="" type="checkbox"/> Low Concentration <input type="checkbox"/> Medium Concentration		④ Ship To: <u>Heard Corporation</u>	
Sample Site Name/Code: <u>m-02</u>		③ SAMPLE MATRIX (Check One) <input type="checkbox"/> Water <input checked="" type="checkbox"/> Soil/Sediment		Attn: _____ Transfer Ship To:	
⑤ Regional Office: <u>IT</u> Sampling Personnel: <u>M. Valenzuela / D. H. Wick</u> (Name) <u>647-7510</u> (Phone) Sampling Date: <u>6/17/83</u> <u>6/21/83</u> (Begin) (End)		⑥ For each sample collected specify number of containers used and mark volume level on each bottle.			
				Number of Containers	Approximate Total Volume
		Water (Extractable)			
		Water (VOA)			
		Soil/Sediment			
		Water (Ext/VOA)			
		Other			
⑦ Shipping Information <u>Federal Express</u> Name of Carrier <u>6-24-83</u> Date Shipped: <u>177-701-132</u> Airbill Number:					
⑧ Sample Description <input type="checkbox"/> Surface Water <input type="checkbox"/> Mixed Media <input type="checkbox"/> Ground Water <input checked="" type="checkbox"/> Solids <input type="checkbox"/> Leachate <input type="checkbox"/> Other (specify) _____			⑨ Sample Location <u>11-02-10</u>		
⑩ Special Handling Instructions: (e.g., safety precautions, hazardous nature)					

ORIGINAL
(Red)

REGIONAL OFFICE FILE COPY

ORIGINAL
(Red)

U.S. ENVIRONMENTAL PROTECTION AGENCY
Hazardous Waste Investigation
Sample Management Office
P.O. Box 818
Alexandria, Virginia 22313
Phone: (703) 557-2490/FTS-8-557-2490

General Directions

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Organic Traffic Reports (OTR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the OTR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of OTR's to the HWI Sample Management Office at (703) 557-2490.

Sampler Directions

1. Note that a separate prenumbered Organics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1-10). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Organics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Regional DPO.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. For samples containing especially hazardous substances, indicate any special handling instructions in the space provided in Item 10, and attach a separate tag bearing the appropriate SMO Sample ID number in addition to the label provided.
5. Fill in shipping information requested in Item 7. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
6. Send the first page of each OTR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
7. Insert the remaining two copies (white and yellow) of the OTR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.



ORGANICS TRAFFIC REPORT

① Case Number:

1836 SAS 6196

Sample Site Name/Code:

m-02

② SAMPLE CONCENTRATION

(Check One)

☒ Low Concentration
☐ Medium Concentration

③ SAMPLE MATRIX

(Check One)

☐ Water
☒ Soil/Sediment

④ Ship To:

MOAD Corp/Chen

Attn:

Transfer

Ship To:

⑤ Regional Office: III

Sampling Personnel:

M. V. ... / D. Hassick

(Name)

5-647-9510

(Phone)

Sampling Date:

6/21/82 6/24/82

(Begin) (End)

⑥ For each sample collected specify number of containers used and mark volume level on each bottle.

	Number of Containers	Approximate Total Volume
Water (Extractable)		
Water (VOA)		
Soil/Sediment	1	80
Water (Ext/VOA)		
Other		

⑦ Shipping Information

Federal Express

Name of Carrier

6-24-83

Date Shipped:

177-2413-2

Airbill Number:

⑧ Sample Description

☐ Surface Water ☐ Mixed Media
☐ Ground Water ☒ Solids
☐ Leachate ☐ Other (specify) _____

⑨ Sample Location

720
ORIGINAL (Red) 02-12

⑩ Special Handling Instructions:

(e.g., safety precautions, hazardous nature)

U.S. ENVIRONMENTAL PROTECTION AGENCY

Hazardous Waste Investigation

Sample Management Office

P.O. Box 818

Alexandria, Virginia 22313

Phone: (703) 557-2490/FTS-8-557-2490

General Directions

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Organic Traffic Reports (OTR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the OTR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of OTR's to the HWI Sample Management Office at (703) 557-2490.

Sampler Directions

1. Note that a separate prenumbered Organics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1 - 10). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Organics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Regional DPO.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. For samples containing especially hazardous substances, indicate any special handling instructions in the space provided in Item 10, and attach a separate tag bearing the appropriate SMO Sample ID number in addition to the label provided.
5. Fill in shipping information requested in Item 7. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
6. Send the first page of each OTR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
7. Insert the remaining two copies (white and yellow) of the OTR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.



ORGANICS TRAFFIC REPORT

① Case Number:

1836 SAS 2614C

Sample Site Name/Code:

m-02

② SAMPLE CONCENTRATION

(Check One)

☒ Low Concentration
☐ Medium Concentration

③ SAMPLE MATRIX

(Check One)

☐ Water
☒ Soil/Sediment

④ Ship To:

M&D Corporation

Attn:

Transfer

Ship To:

⑤ Regional Office:

Sampling Personnel:

M. N. Smith, Jr. D. H. Smith, Jr.
(Name)

617-9510
(Phone)

Sampling Date:

6/21/83

(Begin) (End)

⑥ For each sample collected specify number of containers used and mark volume level on each bottle.

	Number of Containers	Approximate Total Volume
Water (Extractable)		
Water (VOA)		
Soil/Sediment	1	1.0
Water (Ext/VOA)		
Other		

⑦ Shipping Information

Federal Express
Name of Carrier

6-24-83
Date Shipped:

147 201-132
Airbill Number:

⑧ Sample Description

☐ Surface Water ☐ Mixed Media
☐ Ground Water ☒ Solids
☐ Leachate ☐ Other (specify) _____

⑨ Sample Location

m-02-13

⑩ Special Handling Instructions:

(e.g., safety precautions, hazardous nature)

ORIGINAL
(Red)

U.S. ENVIRONMENTAL PROTECTION AGENCY
Hazardous Waste Investigation
Sample Management Office
P.O. Box 818
Alexandria, Virginia 22313
Phone: (703) 557-2490/FTS-8-557-2490

General Directions

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Organic Traffic Reports (OTR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the OTR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of OTR's to the HWI Sample Management Office at (703) 557-2490.

Sampler Directions

1. Note that a separate prenumbered Organics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1 - 10). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Organics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Regional DPO.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. For samples containing especially hazardous substances, indicate any special handling instructions in the space provided in Item 10, and attach a separate tag bearing the appropriate SMO Sample ID number in addition to the label provided.
5. Fill in shipping information requested in Item 7. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
6. Send the first page of each OTR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
7. Insert the remaining two copies (white and yellow) of the OTR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.



ORGANICS TRAFFIC REPORT

① Case Number:

1836 84566196

Sample Site Name/Code:

m-02

② SAMPLE CONCENTRATION

(Check One)

☒ Low Concentration
☐ Medium Concentration

③ SAMPLE MATRIX

(Check One)

☐ Water
☒ Soil/Sediment

④ Ship To:

Apex Corp/Chen

Attn:

Transfer

Ship To:

⑤ Regional Office:

Sampling Personnel:

M. Mel... / D. Hassick

(Name)

687-9510

(Phone)

Sampling Date:

6/21/87

(Begin)

6/21/87

(End)

⑥ For each sample collected specify number of containers used and mark volume level on each bottle.

	Number of Containers	Approximate Total Volume
Water (Extractable)		
Water (VOA)		
Soil/Sediment	1	0.5
Water (Ext/VOA)		
Other		

⑦ Shipping Information

Federal Express

Name of Carrier

6-24-83

Date Shipped:

147 201313200

Airbill Number:

⑧ Sample Description

☐ Surface Water ☐ Mixed Media

☐ Ground Water ☒ Solids

☐ Leachate ☐ Other (specify) _____

⑨ Sample Location

m-02-14

ORIGINAL
(Red)

⑩ Special Handling Instructions:

(e.g., safety precautions, hazardous nature)

U.S. ENVIRONMENTAL PROTECTION AGENCY

Hazardous Waste Investigation

Sample Management Office

P.O. Box 818

Alexandria, Virginia 22313

Phone: (703) 557-2490/FTS-8-557-2490

General Directions

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Organic Traffic Reports (OTR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the OTR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of OTR's to the HWI Sample Management Office at (703) 557-2490.

Sampler Directions

1. Note that a separate prenumbered Organics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1 - 10). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Organics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Regional DPO.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. For samples containing especially hazardous substances, indicate any special handling instructions in the space provided in Item 10, and attach a separate tag bearing the appropriate SMO Sample ID number in addition to the label provided.
5. Fill in shipping information requested in Item 7. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
6. Send the first page of each OTR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
7. Insert the remaining two copies (white and yellow) of the OTR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.



6 3746

ORGANICS TRAFFIC REPORT

① Case Number:

1836 CAS 6/10

Sample Site Name/Code:

M-02

② SAMPLE CONCENTRATION

(Check One)

☐ Low Concentration

☐ Medium Concentration

③ SAMPLE MATRIX

(Check One)

☐ Water

☒ Soil/Sediment

④ Ship To:

MARCO Corp/USA

Attn:

Transfer

Ship To:

⑤ Regional Office:

Sampling Personnel:

M. WOLINSKI

(Name)

215/687-9116

(Phone)

Sampling Date:

6-24-83

6-24-83

(Begin)

(End)

⑥ For each sample collected specify number of containers used and mark volume level on each bottle.

	Number of Containers	Approximate Total Volume
Water (Extractable)		
Water (VOA)		
Soil/Sediment	1	102
Water (Ext/VOA)		
Other		

⑦ Shipping Information

Federal Express

Name of Carrier

6-24-83

Date Shipped:

147201132

Airbill Number:

⑧ Sample Description

☐ Surface Water

☐ Mixed Media

☐ Ground Water

☐ Solids

☐ Leachate

☒ Other (specify) Blank

⑨ Sample Location

M-02-15

⑩ Special Handling Instructions:

(e.g., safety precautions, hazardous nature)

U.S. ENVIRONMENTAL PROTECTION AGENCY
Hazardous Waste Investigation
Sample Management Office
P.O. Box 818
Alexandria, Virginia 22313
Phone: (703) 557-2490/FTS-8-557-2490

General Directions

1. Use only the materials provided to record sample information.
2. Familiarize yourself with all types of information requested of you, and fill in this information completely for each sample taken.
3. Press firmly with ball point pen or pencil, and make sure all information is transferred to carbon pages.
4. Where Organic Traffic Reports (OTR) must be mailed, be sure that all sheets are sent to the correct addressee.
5. These instructions, as well as the address and phone number of the HWI Sample Management Office (SMO) are reproduced for your convenience on the back of each page of the OTR's.
6. Relate any problems and/or questions concerning SMO procedures or the use of OTR's to the HWI Sample Management Office at (703) 557-2490.

Sampler Directions

1. Note that a separate prenumbered Organics Traffic Report must be completed for each point sampled during a given site visit.
2. Fill in all information requested relating to an individual sampling point (Items 1-10). Complete Items 2 and 3, indicating sample concentration and matrix. Note: samples of different concentrations may be assigned to different Organics laboratories, so mark samples and Traffic Reports carefully. If the concentration of a sample is in doubt, contact the Regional DPO.
3. Mark volume level on all sample containers, and identify each container using the appropriate pre-printed label provided. Where necessary, protect the label from water and solvent attack with clear plastic tape.
4. For samples containing especially hazardous substances, indicate any special handling instructions in the space provided in Item 10, and attach a separate tag bearing the appropriate SMO Sample ID number in addition to the label provided.
5. Fill in shipping information requested in Item 7. Immediately upon sample shipment, be sure to notify SMO of all relevant shipping information including shipping date/time, air carrier, airbill numbers, total number of samples taken and containers shipped, and ETA at the laboratory.
6. Send the first page of each OTR (white copy) to the HWI Sample Management Office. Retain the second page (pink copy) for your files.
7. Insert the remaining two copies (white and yellow) of the OTR in a waterproof Ziploc bag and ship along with the corresponding samples to the designated IFB laboratory.